

ERROR MEMORY REPORT

Date: 08/04/11 12:20:37  
ECU: MS420DS0  
JobStatus: OKAY  
Variant: MS420DS0

RESULT: 2 errors in error memory !

83 Signal Crankshaft sensor

Error frequency : 1  
Logistic counter: 26

Engine speed	0.00	1/min
engine condition = engine stoped	1.00	--
oel temperature	52.31	Grad C
Battery Voltage	11.53	V
appear before (rel.)	5.10	h

Signal nicht plausibel  
CARB-Fehler  
Fehler nach Entprellung gespeichert  
Fehler momentan nicht vorhanden  
sporadischer Fehler

Errorcode: 53 B8 01 1A 00 01 7E 71 B8 F9

202 lambda control Bank 1 control block

Error frequency : 2  
Logistic counter: 40

Engine speed	672.00	1/min
temperature cooling water	99.75	Grad C
load	936.90	mg/Hub
lambda probe voltage control probe Bank	1.25	V
appear before (rel.)	4.80	h

Abweichung fett  
CARB-Fehler  
Fehler nach Entprellung gespeichert  
Fehler momentan nicht vorhanden  
sporadischer Fehler

Errorcode: CA B1 02 28 15 C5 AC F9 B8 FC

=====