

VEHICLE DETAILS - 2007 CHRYSLER PT CRUISER LIMITED

VIN:	3A8FY68B37T632699	Body Style:	SW4D	Top Type:	Sun Roof
Ext Color:	CREAM- PWG	Int Color:	TAN- A8KA	Odometer:	18,829
Work Order:	3140593	Seller:	RENTAL CAR FINANCE/GDP	Received Date:	02/06/2008
Sale Number:	15	Lane Number:	30	Run Number:	307
Inspector:	SLINGENSJO 04/09/2008	InService Date:	07/29/2007		

VEHICLE IMAGES**GRADING****4**

Manheim Detroit
600 Will Carleton Rd
Carleton, MI 48117-9704
(734) 654-7100

Clean

Odometer: 18829
 Ext Color: CREAM
 Int Color: TAN
 Engine Starts - Yes



Overall Image
Not Available

VEHICLE INFORMATION**OPTIONS**

- | | | |
|---|---|--|
| <input type="checkbox"/> A/C | <input type="checkbox"/> Power Locks | <input type="checkbox"/> Tilt Steering |
| <input type="checkbox"/> CD Player | <input type="checkbox"/> Power Windows | |
| <input type="checkbox"/> Cruise Control | <input type="checkbox"/> Pwr Seats - Drivers Only | |
| <input type="checkbox"/> Dual Air Bags | <input type="checkbox"/> Pwr Steering | |
| <input type="checkbox"/> Owner's Manual | <input type="checkbox"/> Rear Defrost | |

MECHANICAL

- 4 Cylinder Gas
- Automatic
- Pwr Brakes
- 2.4 L

INTERIOR

- Odometer - 6 Digits Digital -Operable
- Cloth - A8KA
- Interior Condition - Dirty

TIRES AND WHEELS**Wheels:**

Tire	Tread Depth	Brand	Size
Left Front:	7/32"	GOODYEAR	205/55R16
Left Rear:	7/32"	GOODYEAR	205/55R16
Right Front:	7/32"	GOODYEAR	205/55R16
Right Rear:	7/32"	GOODYEAR	205/55R16
Spare:	N/A	(Mini)	N/A

KEYS

- Combo Key - 2

OTHER

- Title State: OH
- Title Received Date: N/A

ADDITIONAL INFORMATION

NAA Federal Emission 45 States , *SSR

DAMAGE SUMMARY AND ADDITIONAL IMAGES

IMAGE	DESCRIPTION	CONDITION	SEVERITY
	Sun Roof	Factory	Acceptable
	Front Mats	Missing	Vsbl Close Insp
	Rear/2nd Row Mats	Missing	Vsbl Close Insp
	Rear Bumper Cover	Scuffed	Vsbl Close Insp

VALUE ADDED REPAIRS APPROVED BY SELLER

Repairs completed by Manheim's professional reconditioning team at the Seller's expense.

Work in Progress: Repair being performed by Manheim

DESCRIPTION	CONDITION	SEVERITY	REPAIR STATUS
Overall Vehicle	Multiple Chips	Vsbl Close Insp	Completed

VIN: 3A8FY68B37T632699, Work Order: 3140593