




Podsumowanie	
Pozycja	Dostępność danych
Analiza numeru VIN	Dostępna
Dane producenta	Dostępne
Dane techniczne	Ilość rekordów: 27
Dekoder VIN	Ilość rekordów: 94
Informacja kradzieżowa	Sprawdzone bazy: 13
Odczyty licznika	Ilość rekordów: 2
Historia pojazdu	Ilość rekordów: 9
Wezwania i akcje serwisowe	Niedostępne
Ostrzeżenia i wydarzenia	Ilość rekordów: 1
Zdjęcia pojazdu	Ilość zdjęć: 49

Ostrzeżenia i wydarzenia	
Ostrzeżenia	
	Pojazd posiadał szkody.
Wydarzenia	
	Dla tego pojazdu nie odnotowano żadnych wydarzeń.

Sprawdzenie i analiza VIN			
Wprowadzony VIN	WF0SXXGBWS9P76707		
Poprawiony VIN	WF0SXXGBWS9P76707		
WMI	WF0	Marka	Ford
VDS	SXXGBWS9	Identyfikator VIS	nie dotyczy
Kod roku	S	Zdekodowany rok	Brak danych
Suma kontrolna	nie dotyczy	Dopasowanie danych	84.64%

Dane producenta	
Producent	Ford Werke AG
Adres	Koeln-Niehl Koeln-Niehl
Region	Europe
Kraj	Germany
Notka	Manufacturer builds more than 500 vehicles per year

Dane techniczne			
 Lista informacji technicznych pojazdu uzyskanych w drodze dekodowania numeru VIN.			
Szczegóły pojazdu			
Marka	Ford	Styl nadwozia	SAV
Model	S-Max / Galaxy	Klasa pojazdu	Medium MPV
Wersja	Brak danych	Typ pojazdu	Medium MPV
Seria	Series 60	Rok modelowy	2006-....
Ilość drzwi	5	Rok budowy	2009
Ilość siedzeń	7-5	Fabryka	Genk Build (Belgium)
Informacje techniczne			
Konfiguracja silnika	Brak danych	Typ paliwa	Diesel
Typ silnika / Wersja silnika	Brak danych / Duratorq	Standard emisji spalin	LDT Stage 4
Kod silnika	Brak danych	Pojemność SI	1753 cc <sup>3</sup>
Układu rozrządu	Brak danych	Pojemność CID	107 Cali sześciennych
Zawory	8	Pojemność Nominalna	1.8 Litra
Cylindry	4	Rodzaj napędu	FWD
Konie Mechaniczne	125 HP	Strona kierownicy	Po lewej
Kilowaty	92 kW	Skrzynia biegów	Ręczna
Doładowanie (turbo/super/diesel)	Bez turbo	Przełożenia	6

## Dekoder VIN



Rozkodowanie numeru VIN, które może zawierać szereg informacji ogólnych o pojeździe, listę opcji wyposażenia standardowego i/lub opcjonalnego pojazdu oraz cechy dodatkowe.  
Dane prezentowane w języku angielskim.

## Informacje ogólne

TRANSMISSION	023F	6 SPEED MANUAL TRANSAXLE - MMT6
ENGINE TYPE	1730	1.8L DURATORQ-TDCI (125PS) - LYNX
BODY STYLE	589	5 DOOR SAV (S-MAX)
VEHICLE LINE	84E	S-MAX/GALAXY 2006-
VERSION	E07	SERIES 60
DRIVE	3C9	LHD FWD
AIR CONDITIONING	59A6	DUAL ZONE AUTO TEMP CONTROL A/C
EMISSION REQUIREMENTS	F93	STAGE 4 REQUIREMENT LDT
BODY STYLE	BF8	5 DOOR SAV

## Wyposażenie standardowe

LUMBAR SEAT SUPPORT PASSENGER SEAT	E61D	WITH PASSENGERS MAN LUMBAR SUPPORT
INTERIOR PACKAGES	AE4	WITHOUT INTERIOR PACK
REAR SPRING LOAD CLASS	DFC	REAR SPRING LOAD CLASS-E
REAR HEADREST TYPE	6EC7	WITH 2 WAY ADJUSTABLE REAR HEADREST
HEADLAMPS - DESIGN	9D9	WITH HALOGEN HEADLAMP
IN CAR ENTERTAINMENT	F331	LOW LEVEL WITH NAV/CD/AM/FM RADIO
FRONT HEATED WASHER JETS	7F2	WITH HEATED WASHER JET
DYNAMIC STABILITY CONTROL	17A	WITH ELECTRONIC STABILITY CONTROL
DOOR HANDLE - EXTERIOR	9DFC	WITH CHROME EXTERIOR DOOR HANDLE
LOAD COMPARTMENT COVER	4DC	WITH LOAD AREA COVER
TRAY/TABLE - FRONT SEAT	A52	WITH TRAY/TABLE - FRONT SEAT
LOAD COMPARTMENT NET	B75	WITHOUT LOAD RETENTION NET
SVO LABEL	D74	WITHOUT SVO APPLICATION/LABEL
RADIO ANTENNA TYPE	F67	WITH TRI BAND ANTENNA
SPECIAL VEHICLE PACK	D49	(-) SVP
STEERING WHEEL TYPE	6A3A	SOFT FEEL TYPE STEERING WHEEL
NAVIGATION DATA	635F	NAVIGATION DATA - COUNTRY SPECIFIC
CARGO STOWAGE DEVICES	96E	WITHOUT CARGO STOWAGE DEVICE
GLOBAL CLOSING	945	WITH GLOBAL CLOSING
FRONT SEAT TYPE	752	SPORTS FRONT SEAT
PASSENGER SEAT ADJUSTMENT TYPE	220	WITH PASS 8 WAY POWER SEAT ADJUSTER
REAR MUDFLAP TYPE	0CA	WITHOUT REAR MUDFLAPS
FRONT PARKING AID	2B9	WITH FRONT PARKING AID
FRONT FOG LAMP TYPE	DC8	WITH FRONT FOG LAMPS
DOOR LOCKING SYSTEMS	03AB	POWER DOOR LOCK WITH ELEC RELEASE
WINDSCREEN GLASS TYPE	F30	INFRARED REFLECTIVE WINDSCREEN
WINDSCREEN WASH/WIPE	E06	WITH AUTOMATIC WINDSCREEN WIPER
FUEL TANK TYPES	819E	WITH 70 LITRE FUEL TANK
CENTRE CONSOLE	DB36	FULL FLOOR CONSOLE WITH ARMREST
DOOR TRIM PANEL LEVEL	8F1B	WITH LEVEL 5 DOOR TRIM PANEL
BRAKE EMERGENCY ASSIST	3A9	WITH BRAKE EMERGENCY ASSIST

TINTED GLASS	2CA	WITH PRIVACY GLASS
HEADER MOUNTED MAP READING LAMPS	402	WITH SUBMARINE LIGHTING-INTERIOR
REAR SHOCK ABSORBER TYPE	7C62	WITH STANDARD REAR SHOCK ABSORBERS
REAR SPOILER TYPE	AF7	WITHOUT SPOILER
FRONT GRILLE TYPES	FD31	WITH SELF COLOUR GRILLE NO.1
FAMILY ENTERTAINMENT SYSTEM	83A	WITHOUT FAMILY ENTERTAINMENT SYSTEM
RADIO SPEAKERS	991F	WITH 8 HIGH SERIES RADIO SPEAKERS
HEATED WINDSCREEN	B30	WITH HEATED WINDSCREEN
AIR CONDITIONING	A7A	WITHOUT AUXILIARY AIR CONDITIONING
WHEEL COVERS	7A3	WITHOUT WHEEL COVERS
BLUE TOOTH INTERFACE CONNECT	6274	BT/VC PHONE INTERFACE + USB CONNECT
SPEED CONTROL	A4A	WITH SPEED CONTROL
TRAILER COUPLING	877	WITH DETACHABLE TRAILER COUPLING
EXTERIOR TAILGATE HANDLE	B5C	BODY COLOURED TAILGATE HANDLE
PLANT BUILD REQUIREMENTS	72C	GENK PLANT BUILD
SEAT SPECIAL COVER REAR	9C23	WITHOUT SPECIAL REAR SEAT COVERS
VOICE ACTIVATED MODULES	0E3C	VOICE ACTIVATED MODULE - BRITISH
INSTRUMENTATION TYPE	33AE	CONVENTIONAL INSTRUMENTS - LEVEL 3
FRONT MUDFLAP TYPE	85A	WITHOUT FRONT MUDFLAPS
WHEEL SIZE & STYLE	C44	7J X 17" STYLE 5 ALLOY WHEEL
SPARE WHEEL TYPE	CAA	WITHOUT SPARE WHEEL
VP LABEL	9EB	VP APPLICATION LABEL
DRIVERS SEAT ADJUSTMENT TYPE	C534	DRV POWER SEAT ADJUST WITH MEMORY
REAR VIEW MIRROR TYPE	EC42	ELECTRIC OPERATED REAR VIEW MIRROR
SPECIAL EQUIPMENT PACKAGES	392	WITHOUT SPECIAL EQUIPMENT PACKAGE
LIFTGATE	3EE	WITH STANDARD LIFTGATE
REAR WINDOWS	2CC	WITH FIXED REAR WINDOW
EXTERIOR MIRROR DUAL	9D0	DUAL EXT MIRROR-P/HT/MEM/FOLD BACK
SEAT PACK	D24	WITHOUT SEAT PACK
SUSPENSION TYPES	EE1	WITH STANDARD SUSPENSION
SEAT SPECIAL COVER FRONT	F523	WITHOUT SPECIAL FRONT SEAT COVERS
AUXILIARY HEATER	E7D	WITH SUPPLEMENTAL AIR HEATER
WHEEL LUG NUTS	3F6	NON LOCKING LUG NUTS
17 INCH TYRES	7765	225/50 R 17 W TYRE
DRV SEAT BACK TABLE	9705	DRV SEAT BACK FOLD DOWN TABLE
HEADLAMP CONTROL	498	WITH AUTOMATIC HEADLAMP ON/OFF
LUMBAR SEAT SUPPORT DRIVER SEAT	0E1D	WITH DRIVERS MANUAL LUMBAR SUPPORT
FRONT SPRING LOAD CLASS	AFA	FRONT SPRING LOAD CLASS-H
LUGGAGE COMPARTMENT NET KIT	4758	WITHOUT LUGGAGE COMPARTMENT NET KIT
RAPID SPEC OPTION - EAO	425	WITHOUT DRESS UP RSO
INSTRUMENT PANEL	74B	WITH TUTONE INSTRUMENT PANEL
PARKING BRAKE - FUNCTION TYPE	FB9	WITH MECHANICAL PARKING BRAKE
RR OVERHEAD READING LAMP	4A28	WITH 2ND ROW READING LAMPS
REAR WINDOW OPERATION	4CA	WITH ELECTRIC REAR WINDOWS
DOOR REMOTE CONTROL UNIT	1D9A	DOOR ENTRY R/CONT UNIT-2 FLIP KEYS
REVERSE PARKING AID	FB9	WITH REAR PARKING AID
2ND ROW SEATING	2E2B	SECOND ROW - 3 INDIVIDUAL SEATS
OVERHEAD CONSOLE	CDB	WITH STANDARD OVERHEAD CONSOLE
BATTERIES	2ED	80 AH BATTERY
LUGGAGE COMPARTMENT MAT	6FA	LUGGAGE COMPARTMENT REVERSIBLE MAT

ANTI-LOCK BRAKES	CE0A	4 WHEEL ANTI-LOCK BRAKING SYSTEM
INTERIOR PARTITION	0E3	WITHOUT INTERIOR PARTITION
AIR CONDITIONING - HEAVY TRUCK	97A	WITHOUT AIR CONDITIONING
12 INCH TYRES	7765	225/50 R 17 W TYRE

## Informacja kradzieżowa



Sprawdzenie wewnętrznych i zewnętrznych rejestrów oraz baz danych pojazdów skradzionych.

Stan	Typ rejestru/bazy danych	Wynik przeszukiwania
<input checked="" type="checkbox"/>	Ewidencja skradzionych pojazdów w USA	Pojazd nie figuruje w rejestrze
<input checked="" type="checkbox"/>	Ewidencja skradzionych pojazdów Kanadyjskiej Policji	Pojazd nie figuruje w rejestrze
<input checked="" type="checkbox"/>	Internetowa ewidencja skradzionych pojazdów CrimiMail	Pojazd nie figuruje w rejestrze
<input checked="" type="checkbox"/>	Ewidencja skradzionych pojazdów Czeskiej Policji	Pojazd nie figuruje w rejestrze
<input checked="" type="checkbox"/>	Ewidencja skradzionych pojazdów w Niemczech	Pojazd nie figuruje w rejestrze
<input checked="" type="checkbox"/>	Ewidencja skradzionych pojazdów w Norwegii	Pojazd nie figuruje w rejestrze
<input checked="" type="checkbox"/>	Ewidencja skradzionych pojazdów Włoskiej Policji	Pojazd nie figuruje w rejestrze
<input checked="" type="checkbox"/>	Ewidencja skradzionych pojazdów Kaynine	Pojazd nie figuruje w rejestrze
<input checked="" type="checkbox"/>	Ewidencja skradzionych pojazdów Litewskiej Policji	Pojazd nie figuruje w rejestrze
<input checked="" type="checkbox"/>	Ewidencja skradzionych pojazdów Holenderskiej Policji	Pojazd nie figuruje w rejestrze
<input checked="" type="checkbox"/>	Ewidencja skradzionych pojazdów Rumuńskiej Policji	Pojazd nie figuruje w rejestrze
<input checked="" type="checkbox"/>	Ewidencja skradzionych pojazdów w Szwecji	Pojazd nie figuruje w rejestrze
<input checked="" type="checkbox"/>	Ewidencja skradzionych pojazdów Słoweńskiej Policji	Pojazd nie figuruje w rejestrze
<input checked="" type="checkbox"/>	Ewidencja skradzionych pojazdów Słowackiej Policji	Pojazd nie figuruje w rejestrze
<input checked="" type="checkbox"/>	Ewidencja skradzionych pojazdów w Rosji	Pojazd nie figuruje w rejestrze
<input checked="" type="checkbox"/>	Ewidencja skradzionych pojazdów w Danii	Pojazd nie figuruje w rejestrze
<input checked="" type="checkbox"/>	Ewidencja skradzionych pojazdów IAATI oraz Automo.pl	Pojazd nie figuruje w rejestrze

### Historia pojazdu

Sprawdzenie historii pojazdu.

Data	Przebieg	Źródło	Opis
2009-04		Niezależne	{"message": "An unhandled exception occurred."}
2010-11-04	43 297 km	Niezależne	Odnotowano szkodę pojazdu na kwotę: 267,50 EUR w kraju: .
2011-12		Niezależne	POJAZD OFEROWANY DO SPRZEDAŻY - EUROPA
2011-12	75 101 km	Niezależne	Pojazd wystawiony na sprzedaż.
2012-02		Niezależne	Pojazd oferowany na sprzedaż na: AUKCJI INTERNETOWEJ w (Belgia), BELGIA
2012-02		Niezależne	Kolor pojazdu: SREBRNY, WNĘTRZE:
2012-02		Niezależne	Kraj pochodzenia: BELGIA
2012-02		Niezależne	Pojazd wystawiony na sprzedaż.
2012-04		Niezależne	POJAZD ZNALEZIONY W ZASOBACH INTERNETOWYCH. KONTROLA POJAZDU.

### Zdjęcia pojazdu

Zestawy zdjęć pogrupowane są według dat ich publikacji.

Data      Galeria

2012-02-03


[https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF0SXXGBWS9P76707\\_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46\\_01.JPG](https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF0SXXGBWS9P76707_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46_01.JPG)

[https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF0SXXGBWS9P76707\\_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46\\_02.JPG](https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF0SXXGBWS9P76707_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46_02.JPG)

[https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF0SXXGBWS9P76707\\_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46\\_03.JPG](https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF0SXXGBWS9P76707_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46_03.JPG)



([https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707\\_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46\\_04.JPG](https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46_04.JPG))



([https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707\\_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46\\_05.JPG](https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46_05.JPG))



([https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707\\_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46\\_06.JPG](https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46_06.JPG))



([https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707\\_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46\\_07.JPG](https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46_07.JPG))



([https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707\\_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46\\_08.JPG](https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46_08.JPG))



([https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707\\_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46\\_09.JPG](https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46_09.JPG))



([https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707\\_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46\\_10.JPG](https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46_10.JPG))



([https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707\\_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46\\_11.JPG](https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46_11.JPG))



([https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707\\_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46\\_12.JPG](https://www.vin-info.com/vehicle-picture/c4c89c4a-28dd-4a21-9042-cc8ee906039f;WF05XXGBWS9P76707_6EAF92D0-4EA7-11E1-970F-6C626D3F7D46_12.JPG))

2012-04-06



([https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a;image\\_51cb7320ec249.jpg](https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a;image_51cb7320ec249.jpg))





(<https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a>;image\_51cb7320ec258.jpg)



(<https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a>;image\_51cb7320ec264.jpg)




(<https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a>;image\_51cb7320ec26f.jpg)



(<https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a>;image\_51cb7320ec27b.jpg)



(<https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a>;image\_51cb7320ec286.jpg)



(<https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a>;image\_51cb7320ec291.jpg)



(<https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a>;image\_51cb7320ec29c.jpg)



(<https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a>;image\_51cb7320ec2a7.jpg)



(<https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a>;image\_51cb7320ec2b2.jpg)



(<https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a>;image\_51cb7320ec2bc.jpg)



(<https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a>;image\_51cb7320ec2c6.jpg)



(<https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a>;image\_51cb7320ec2d1.jpg)



([https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a;image\\_51cb7320ec2dc.jpg](https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a;image_51cb7320ec2dc.jpg))



([https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a;image\\_51cb7320ec2e7.jpg](https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a;image_51cb7320ec2e7.jpg))



([https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a;image\\_51cb7320ec2f2.jpg](https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a;image_51cb7320ec2f2.jpg))



([https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a;image\\_51cb7320ec2fd.jpg](https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a;image_51cb7320ec2fd.jpg))



([https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a;image\\_51cb7320ec308.jpg](https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a;image_51cb7320ec308.jpg))



([https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a;image\\_51cb7320ec313.jpg](https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a;image_51cb7320ec313.jpg))



(<https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a>;image\_51cb7320ec31e.jpg)



(<https://www.vin-info.com/vehicle-picture/fbb08e9f-23df-4b40-8edb-a470444a8a8a>;image\_51cb7320ec329.jpg)

2012-04-06



(<https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc>;image\_51cb73215f55a.jpg)



(<https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc>;image\_51cb73215f566.jpg)



(<https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc>;image\_51cb73215f56e.jpg)



(<https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc>;image\_51cb73215f576.jpg)



([https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image\\_51cb73215f57e.jpg](https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image_51cb73215f57e.jpg))



([https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image\\_51cb73215f58e.jpg](https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image_51cb73215f58e.jpg))



([https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image\\_51cb73215f58e.jpg](https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image_51cb73215f58e.jpg))



([https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image\\_51cb73215f596.jpg](https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image_51cb73215f596.jpg))



([https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image\\_51cb73215f59d.jpg](https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image_51cb73215f59d.jpg))



([https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image\\_51cb73215f5a4.jpg](https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image_51cb73215f5a4.jpg))



([https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image\\_51cb73215f5ac.jpg](https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image_51cb73215f5ac.jpg))



([https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image\\_51cb73215f5b3.jpg](https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image_51cb73215f5b3.jpg))



([https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image\\_51cb73215f5ba.jpg](https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image_51cb73215f5ba.jpg))



([https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image\\_51cb73215f5c1.jpg](https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image_51cb73215f5c1.jpg))



([https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image\\_51cb73215f5c8.jpg](https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image_51cb73215f5c8.jpg))



([https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image\\_51cb73215f5d0.jpg](https://www.vin-info.com/vehicle-picture/1f07c57f-4719-4123-851a-8b74540af6bc;image_51cb73215f5d0.jpg))

#### Ograniczone oświadczenia i zapewnienia oraz uwagi od użytkowników

Nie gwarantujemy, że dane dostępne na Stronie, w tym Dane Pojazdu, są kompletne oraz prawidłowe, ani nie zapewniamy, że Strona będzie stale dostępna, lub że treści dostępne na Stronie, wliczając Dane Pojazdu, będą aktualne.

Generujemy Dane Pojazdu wyłącznie na podstawie danych, które posiadamy w Bazie Danych w momencie zlecenia dostarczenia Danych Pojazdu. Dlatego w przypadku korzystania z jakichkolwiek usług na Stronie może się zdarzyć, że niektóre żądane informacje nie będą dostępne lub mogą nie być aktualne lub prawidłowe. Nie ponosimy odpowiedzialności za takie braki informacji w Danych Pojazdu, lub brak możliwości wygenerowania Danych Pojazdu w związku z brakiem żądanych informacji w Bazie Danych lub tym, że są nieaktualne.

Specyfikacja pojazdu dostępna w Danych Pojazdu oparta jest na odkodowaniu Numeru VIN (który identyfikuje producenta pojazdu i informacje pojeździe). Dlatego specyfikacja ta nie wykaże zmian dokonanych w konkretnym pojeździe po jego wyprodukowaniu. Nadto nie gwarantujemy prawidłowości odkodowania tego numeru.

W przypadku użytkowników niebędących Konsumentami, w granicach przewidzianych prawem właściwym nie składamy żadnych zapewnień, nie udzielamy gwarancji co do jakości, wyłączamy rękojmię oraz nie składamy zapewnień co do standardów wykonywania usług na Stronie i korzystania ze Strony (w szczególności wyłączamy wszelkie gwarancje i nie składamy żadnych zapewnień przewidzianych w obowiązującym prawie odnośnie satysfakcjonującej jakości, przydatności do celu lub zachowania należytej staranności i umiejętności).

W przypadku zauważenia problemów technicznych na Stronie lub zauważenia niekompletności lub nieaktualności informacji dostarczanych przez nas, jak i wszelkich skarg dotyczących Strony, należy niezwłocznie nas powiadomić przez użycie formularza na stronie "Kontakt" lub przez napisanie do nas wiadomości na adres e-mail [info@automo.pl](mailto:info@automo.pl). W uzasadnionych przypadkach odpowiemy na wiadomość niezwłocznie.

---

» [F.A.Q. \(/faq\)](#)    » [Regulamin serwisu \(/regulamin\\_serwisu\)](#)    » [Polityka prywatności i Cookies \(/polityka-prywatnosci\)](#)    » [Kontakt \(/kontakt\)](#)

© 2010-2017 Automo.pl - Historia pojazdu. Wszelkie prawa zastrzeżone.