

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	174563 KM
<b>File nr. :</b>	811397	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
RN5288 / WAUZZZ8K39A048510 /		<b>yr of constructionr :</b>	2008
<b>E-File nr. :</b>		<b>First registration :</b>	08/07/2008
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	AUDI / A4	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	ONBEKEND	<b>Fuel :</b>	
<b>Classification :</b>	G	<b>Environment Class:</b>	
<b>Customer company :</b>	KB LUX SA	<b>Co2:</b>	g/km
<b>Driver :</b>		<b>Transponder :</b>	No
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>Original registr. number :</b>	OK	<b>Service manual :</b>	OK
<b>Cert. of registration :</b>	NOK [x]	<b>Cert. of conformity :</b>	OK
<b>Cert. of registration copy :</b>	OK [x]	<b>Insurance certificate :</b>	NOK [x]
<b>Warning vest :</b>	OK [x]	<b>Transport licence :</b>	
<b>Tax certificate :</b>		<b>Navigation CD/SD/DVD</b>	OK [x]
<b>Fuel card :</b>		<b>Car radio :</b>	OK [x]
<b>Mobile phone kit :</b>	NOK [x]	<b>Extinguisher :</b>	OK [x]
<b>First aid kit :</b>	OK [x]	<b>Warning triangle :</b>	OK [x]
<b>Jack, wheelspanner :</b>	OK [x]	<b>Oil level :</b>	
		<b>Filled up :</b>	0

## Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	
Wheel RES:	[x]	MICHELIN	Tyre :	OK		>6 /	Rim :	/	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	16	M+S
Rear tyre	225	55	R	16	M+S

Remark :

## Wheels and tyres:

Wheel FL:			Tyre :	OK	>6 /	Rim :	/	Hubcap :
Wheel RL :			Tyre :	OK	>6 /	Rim :	/	Hubcap :
Wheel FR :			Tyre :	OK	>6 /	Rim :	/	Hubcap :
Wheel RR :			Tyre :	OK	>6 /	Rim :	/	Hubcap :
Wheel RES:			Tyre :	OK	>6 /	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: NOT ACCEPTABLE

### Bodywork & windows

[x]		REAR THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			
Number	Code	Description	Unit price	Depr.	Total	
1	I1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR	
[x]		REAR DOOR/RIGHT/CENTER	DENT / CHIPS			
		Repair paint - LI	New paint - E	Depr.	Total	
2	30 LU =144.00 EUR	0 EUR	435.72 EUR	50 %	579.72 EUR	
[x]		REAR THRESHOLD/RIGHT/REAR	DENT / CHIPS			
		Repair paint - LI	New paint - E	Depr.	Total	
2	0 LU =0.00 EUR	310.50 EUR		50 %	310.50 EUR	

### Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	DOOR REAR RIGHT	367.20 EUR	50 %	367.20 EUR

1	2	3	4	5	6	7	8	9	10
115.56	1257.42	0	0	0	0	0	0	0	0
115.56	628.71	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
115.56	1257.42	0	<b>1372.98</b>
HOG: 0	BG: 0		NA Deprec. 744.27
			0.00%
			<b>TOTAL 744.27</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

## Prices in EUR without VAT

Authorized by customer :  Remark authorized customer :  Date : 15/04/2012      Hour : 16:36 Company : Name : E-Mail : @	Name : MICHEL DE DEYN
Signature authorized by customer	Signature authorized by commissioner (VAB Fleet Services)
	