



parametry pojazdu

3:02

23.12.2010

			Oryginal	Spec. uzytk
Nr nadwozia	WVWZZZ6NZ1Y092868	numer silnika	AUD	
typ handlowy	6N22A4	numer skrzyni bie	ETD	
Rok modelowy	2001	numer napędu osio	5S	
model	PO	wyposazenie	UX	
Oznaczenie modelu	polo	kolor dachu	8E	
		kolor zewnetrzny/numer kol	8E/A7W	

numery PR

A8C	Comfort equipment
B08	Type approval France
B0A	Component parts set without country-specific design requirement
C09	Operating permit, alteration
C8E	Steel wheels 6J x 14
E0A	No special edition
F0A	No special purpose vehicle, standard equipment
G0C	5-speed manual transmission
H2Y	Tires 185/55 R14 H
J1L	Battery 280 A (60 Ah)
K8G	Hatchback
L0L	Left-hand drive vehicle
MH5	4-cyl. gasoline engine 1.4 L/44 kW multi-point injection base engine is T8H/T1X
N2P	Fabric seat covering
PB5	
PE1	
PF0	
PH1	
Q1X	Sports front seats with integrated storage trays
QS0	Without electronic map cooling system
RBH	
T8H	4-cylinder gasoline engine 1.4 L unit 030.R (aluminum)
U0C	Instrument insert with tachometer clock and km/h speedometer
V0A	Tires w/o specification of tire brand
0A1	2 doors
0AB	Front stabilizer
0BA	Without rear stabilizer
0DH	Vehicle class differentiation 6N0
0F2	Fuel system for carburetor gasoline engine
0FB	Pamplona manufacturing sequence
0GG	Emission standard EU4
0JZ	Without determination of weight category for front axle
0KA	Without stickers and badges



parametry pojazdu

3:02

23.12.2010

numery PR

0L2 Electric throttle actuation
0NB Nameplate set in base trim
ORA Without ignition/starter switch locking system
0SG Labels/plates in French
0TD Front and rear floor mats
0UA Without special color trim
0VB Information kit in French
0Y1 Standard climatic zones
1AC Anti-lock brake system (ABS)
1C1 Antifreeze up to -25 degree celsius tolerance up to -30 degree C
1E1 Activated carbon canister
1EX Special identification plate for EC for M1 passenger vehicle
1G6 Space-saving spare wheel
1GA Front shock absorption, basic design 1
1JA Rear shock absorption, basic design 1
1K1 Mechanical clutch actuation
1KH Drum brakes, rear
1LM Disc brakes, front
1MZ Steering wheel for air bag system
1N1 Power steering
1NV Full wheel covers
1S4 Tool kit with special jack
1T0 Without first aid kit and warning triangle
1Z0 Initial standard fuel filling
2B0 Without additional exterior noise suppression
2G1 Insert for the filling up of unleaded fuel
2JJ Painted bumpers with protective moldings
2LB Fuel tank with special material treatment
2V1 Dust and pollen filter
2WA Without additional tires
3B0 Without additional child seat anchor
3C1 Static lap belt, center rear
3CA Without partition
3FA Without roof insert (standard roof)
3GA Without cargo area
3H3 Backrest release for front seat(s)
3J7 Articulated and height-adjustable headrests for front seats
3L3 Manual height adjustment for front seats
3LD Door and side trim panel
3NC Rear seat bench/backrest, split folding
3Q1 Rear headrests
3QT 3-point seat belts with tensioner and height adjustment, front
3U1 Foldable trunk cover
3ZB 3-point seat belts, outer rear with ECE label



parametry pojazdu

3:02

23.12.2010

numery PR

4A0 Without seat heater
4B2 Body-colored protective side molding
4GF Windshield in heat-insulating glass
4K0 Radio remote controlled central locking
operated from inside
4KC Side and rear windows in heat-insulating
glass
4L2 Dipping breakaway interior rear view
mirror
4M5 Cup holder
4N2 Standard dashboard
4Q0 No flame retardent materials
4R1 Power windows
4UE Air bag for driver and front seat
passenger
4W0 Without cassette and CD storage unit
4X0 Without side air bag
5C0 Without special body measures
5D1 Carrier frequency 433.92 MHz-434.42 Mhz
5J0 Without rear spoiler
5K0 Without surface protection, with
additional transit coating
5L1 Front spoiler
5RQ Right exterior mirror: convex
5SL Left exterior mirror: aspherical
5VA Without cargo area front
6EJ Additional body cover on sill without
wheel arch
6FK Body-colored add-on parts
6KC Radiator grille
6N0 Without mud flaps
6PA Plastic hand brake lever handle
6Q1 Plastic gearshift knob/handle
6R1 Leatherette gearshift boot
6SE Flat needle-punched trunk floor covering
6U0 Without additional seals outside
6XB Exterior mirrors: adjustable from inside
6Y0 Without cruise control warning system
7A0 Without CD changer/CD player
7B2 12-volt socket in luggage boot
7E0 W/o heat accumulator/auxiliary heating
7Q0 Without navigation device
7QA Without CD/DVD for navigation
7R3 Side turn signal lights (white)
8AQ Radio "beta"
with removable operating panel
8BB Halogen headlight
for driving on the right
8CC Speedometer sensor without seal
(electronic speedometer sensor)
8E2 Local interference suppression for FM/AM
radio reception
8GD Alternator 90A
8K0 Without special headlight



parametry pojazdu

3:02

23.12.2010

numery PR

activation
8N1 Windshield wiper intermittent control
8Q1 Headlight-range adjustment
8QE Key for locking system
with remote control
8R1 Center high-mounted stop light
8RE 4 speakers (passive)
8SB Taillight assembly w/ dark colored lens
8TC Rear fog light for driving on the right
8WA Without front fog light
8X0 Without headlight washer system
8Y0 Single-tone horn
9AB Manually controlled air conditioning
9P0 Without seat belt reminder
9T0 Without heated washer nozzles
9V7 Electronic vehicle immobilization device
with anti-theft alarm system and
passenger compartment control
9W0 W/o car phone preparation/installation
9Y0 Without outdoor temperature gage

GURRAL